


P.E.P. TECHNOLOGY[®]

5 AXIS BEVELING SOFTWARE


The FASTEST....EASIEST....SOLID GRAPHICS BEVELING SOFTWARE with INSTANT 3D VERIFICATION

The P.E.P. Beveling software allows the user to mark selected geometry on a 2D flat drawing and see the actual 3D finished cutter path in seconds. The process below of creating the finished cutter path takes 20 seconds.

FROM THIS:




TO THIS:




The step by step process.


Step 1. Select the drawing.




Step 2. Select the type of BEVEL.



Step 4. Verify the results



Step 3. Enter the appropriate parameters



Step 5. Rotate and Verify in 3D mode

